

c/sf

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Chama Petroleum Company ✓
3. ADDRESS OF OPERATOR
5447 Glen Lakes Dr., Dallas, Texas 75231
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FNL & 1980' FEL of Sec. 3
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) 4 1/2" Casing	

5. LEASE
NM-14758
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
RECEIVED
7. UNIT AGREEMENT NAME
NOV 22 1982
8. FARM OR LEASE NAME
Huber Federal
9. WELL NO.
#2 O. C. D. ARTESIA, OFFICE
10. FIELD OR WILDCAT NAME
Undesignated (Morro)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3, T-20-S, R-25-E
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3465.2' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

1982

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-4-82: Ran 249 joints 4 1/2" 8 rd. thread, 11.6# casing set at 9666' K.B., all casing drifted & hydrostatic tested to API prior to running using torque recorded, cemented with Halliburton spearheaded 500 gals. mud flush, cemented with 175 sacks Class H at 7 1/2 bbls. per min., plugged down at 6:15 P.M., New Mexico time, float held, released rig at 2:30 A.M. 11-4-82. Ran temperature survey at 7:00 A.M. 11-4-82, indicated top of cement outside casing at 9050', plugged back total depth 9652' by wireline.

11-5-82 thru 11-15-82: Waiting on Completion

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Glass TITLE President DATE 11-15-82

ACCEPTED FOR RECORD

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL: NOV 19 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side