

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Drilled at
Artesia, NM

85210 ASE NM 34905

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.

1. oil well ☐ gas well ☒ other ☐ MAR 11 1983
2. NAME OF OPERATOR
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
Artesia, NM OFFICE
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FNL & 1980 FWL, Sec. 8-19S-27E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*

(other) Production Casing, Perforate, Treat

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Eastern Shore TL Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit C, Sec. 8-T19S-R27E

12. COUNTY OR PARISH

13. STATE

Eddy

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3275' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

MAR 15 1983

MINERALS MANAGEMENT SERVICE
ROSVILLE, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ED 10002'. Ran 231 jts of 4-1/2" 11.6# N-80 and K-55 casing as follows: 45 jts of 4-1/2" 11.6# N-80; 155 jts 4-1/2" 11.6# K-55 and 31 jts 4-1/2" 11.6# N-80 casing set at 10020'. 1-regular guide shoe set 10020'. Float collar set 9998'. Cemented w/230 sx Class "H", .6% CP-9, .3% TF-4, .2% AF-S and 2% KCL. Compressive strength of cement - 975 psi in 12 hrs. PD 2:00 AM 3-11-83. Bumped plug to 1450 psi, released pressure and float head okay. WOC 18 hrs. WIH and perforated 9751-58' w/14 .40" holes. Ran tubing and packer dry. Set packer at 9713'. Acidized perfs w/2000 gallons 7 1/2% MF acid, N₂ and ball sealers. Flowing back and recovering load.

Subsurface Safety Valve: Manul. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED: *David R. Glass* Production Supervisor

DATE 3-24-83

ACCEPTED FOR RECORD

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY
CONDITIONS OF APPROVAL

MAR 23 1983

DATE

MINERALS MANAGEMENT SERVICE
ROSVILLE, NEW MEXICO

*See Instructions on Reverse Side