			ASÍ
Form 3160-5 June 1990)	UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAI	INTERIOR 811 S. 1st Street	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	SUNDRY NOTICES AND REP	ORTS ON WELLS	NM-A-34905
Do not use this fo U		pen or reentry to a different reserve	
	SUBMIT IN TRIPL	CATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil X Gas Well X Well	Duher	and the second	8. Well Name and No.
2. Name of Operator	LEUM CORPORATION	(505) 748-1471)	Eastern Shore TL Fed #1 9. API Well No.
3. Address and Telephone N			30-015-24282
105 South 4th St., Artesia, NM 88210 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area McMillan Upper Penn
	1980' FWL of Section 8-TI	S-R27E (Unit C, NENW)	11. County or Parish, State
			Eddy Co., NM
2 CHECK	APPROPRIATE BOX(s) TO IND	CATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF	TYPE OF SUBMISSION TYPE OF ACTION		
Notice o	fIntent	Abandonment	Change of Plans
		Recompletion	
X Subseque	ent Report	Plugging Back     Casing Repair	Water Shut-Off
Final Ab	pan-lonment Notice	Altering Casing	Conversion to Injection
		I Other Pull RBP to commin	
	mp eted Operations (Clearly state all pertinent detail stions and measured and true vertical depths for all		starting any proposed work. If well is directionally drilled,
annulus to 15 lock nuts on 1-1-2-97 - B1 2 locking nut release packe 1-3-97 - Pump tools. Went Cut tubing at tubing. TIH tubing. Latc Released grap 1-4-97 - TOH overshot with N-80 workstri on fish. TOO of pin. Shut 1-5-97 - TIH	00 psi for 10 minutes. H tubinghead. Shut in. ed well down. Pumped 30 s off tubinghead. Opened r. Flanged up. Loaded a ed 30 bbls 2% KCL down to through packer - free poi 7565'. TOOE with wirels with 3-3/4" overshot, bun hed onto fish. Jarred 2- ple. Shut well in. with 2-3/8" J-55 products 2-3/8" grapple, bumper a ng. Latched onto fish. H - had 15' tubing, seats well in. with 3-3/4" OD impression foregoing is too and correct	nt - tubing stuck at packe ne. Nippled down tree. N per sub, jars, accelerator 1/2 hours - did not come 1 on string, drill collars, sub, jars, drill collars an Set jars off 4 times at 80 ng nipple & collar. Mandr block on sandline. Tagge CO te_Operations Technician	tubing. Could not loosen Picked up on tree. Cut d 2-1/2 hours - could not reline. TIH with free point r. TOOH. TIH with cutter. ippled up BOP. TOOH with sub, drill collars and oose. Jars quit working. jars and overshot. TIH with d accelarator sub on 2-3/8" 000# - came loose. Set down el of packer parted in thread d fish. TOOH - good imprint NTINUED ON NEXT PAGE: 
Approved by Conditions of approval,	if any: Ti		Date
		TPG. SCD.) DAVID R. GLAN	
	<ol> <li>makes it a crime for any person knowingly and matter within its jurisdiction.</li> </ol>	villfully to make to any department or agency of the	United States any false, fictitious or fraudulent statements
	*See	Instruction on Release Side	