

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 660 FSL & 2310 FEL, Sec. 5-19S-27E
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) Run 7" casing.			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 197 joints of 7" 26# and 23# N-80 and J-55 LT&C casing as follows: 12 joints 7" 26# N-80 LT&C; 82 joints 7" 26# J-55 LT&C; 103 joints 7" 23# J-55 LT&C (total 7928') casing set 7920'. 1-regular guide shoe set 7920'. Insert float set 7884'. Cemented w/460 sacks Class "H", 1% Flo-lok, 1/4#/sack celloseal and 3#/sack Hiseal. Compressive strength of cement - 900 psi in 12 hrs. PD 2:30 PM 10-29-83. Bumped plug to 1500 psi, released pressure and float held okay. Cement did not circulate. WOC. Drilled out 8:30 PM 10-30-83. WOC 18 hrs. Nippled up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 6-1/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Quintanilla TITLE Production Supervisor DATE 11-3-83

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY SWG TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF MAY 7 1984

ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

5. LEASE
NM 30629
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Eastern Shore XM Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Undes. Morrow
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit 0, Sec. 5-T19S-R27E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3275' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

