


|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |



4. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Chama Petroleum Company

3. Address of Operator  
P.O. Box 31405, Dallas, Texas 75231

4. Location of Well  
UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE West LINE, SECTION 27 TOWNSHIP 19 South RANGE 25 East N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

South Boyd

9. Well No.

1

10. Field and Pool, or Wildcat

Und. Cemetery Morrow

15. Elevation (Show whether DF, RT, GR, etc.)

3455.7 G.L.

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER Drilling Activity - Surf. & Int. Cag. ☐

17. Description Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-28-82: Spudded at 12:00 noon 8-27-83, waited on cement at 373' for 4 hrs., Survey at 373' was 3/4°, P.P. 700, RPM 90, drilling with clear water, lost circulation at 90', ran 10 joints 13 3/8" casing, plugged down at 12:45 A.M.

8-29-83: At 630', made 257' in last 24 hrs., P.P. 800, RPM 64, Wt. on Bit 50,000, lost circulation under surface pipe, drilling with clear water, pumped no returns.

8-30-83: At 1060', made 430' in last 24 hrs., Survey at 746' was 3/4°, P.P. 900, RPM 64, Wt. on Bit 50,000, no returns.

8-31-83: At 1320', made 260' in last 24 hrs., Survey at 1070' was 1/2°, Survey at 1320' was 1/2°, P.P. 900, RPM 64, Wt. on Bit 50,000, no returns, Ran 32 joints 8 5/8" casing.

9-1-83: At 1320', no footage in last 24 hrs., ran Temperature Survey (top of cement at 410' & tag inside at 1258'), cemented 4 times with 1" pipe, circulated cement to surface, waited on cement 1 1/4 hrs.

9-2-83: At 1920', made 600' in last 24 hrs., Survey at 1820' was 3/4°, M.W. 8.4, Vis. 28, PH 9.5, P.P. 1200, Strokes 94, RPM 64, Wt. on Bit 45,000

TIGHT HOLE - PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL!

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lathin Craft

TITLE Prod. Secretary

DATE 9-2-83

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: