

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2000
SANTA FE, NEW MEXICO 87501

RECEIVED BY

SEP 15 1983

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-7

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER	5a. Indicate Type of Lease State ☐ Fee ☒
2. Name of Operator Chama Petroleum Company	7. Unit Agreement Name
3. Address of Operator P.O. Box 31405, Dallas, Texas 75231	8. Farm or Lease Name South Boyd
4. Location of Well UNIT LETTER <u>F</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>19</u> South RANGE <u>25</u> East N.M.P.M.	9. Well No. 1
15. Elevation (Show whether DF, RT, GR, etc.) 3455.7 G.L.	10. Field and Pool, or Wellbore Und. Cemetery Morrow
	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐ Drilling Activity - Surf. & Int. Csg.	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, any proposed work) SEC RULE 1103.

- 9-2-83: At 1920', made 600' in last 24 hrs., Survey at 1820' was 3/4°, M.W. 8.5, Vis. 28, PH 9.5, P.P. 1200, Strokes 94, RPM 64, Wt. on Bit 45,000
- 9-3-83: At 2612', made 692' in last 24 hrs., Survey at 2320' was 3/4°, M.W. 8.4, Vis. 28, PH 9.5, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-4-83: At 3255', made 643' in last 24 hrs., Survey at 2794' was 1°, M.W. 8.4, Vis. 28, PH 10, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-5-83: At 3753', made 498' in last 24 hrs., Survey at 3290' was 3/4°, M.W. 8.4, Vis. 28, PH 9, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-6-83: At 4162', made 409' in last 24 hrs., Survey at 3753' was 1°, M.W. 8.4, Vis. 28, PH 9.5, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-7-83: At 4560', made 398' in last 24 hrs., Survey at 4250' was 1/2°, M.W. 8.4, Vis. 28, PH 10, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-8-83: At 5024', made 464' in last 24 hrs., Survey at 4744' was 3/4°, M.W. 8.4, Vis. 28, PH 9.5, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole
- 9-9-83: At 5455', made 431' in last 24 hrs., Survey at 5270' was 3/4°, M.W. 8.4, Vis. 28, P.P. 1200, RPM 64, Wt. on Bit 45,000, 18 collars in hole

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kathie Craft TITLE Secretary DATE Sept. 9, 1983

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: