


LYNES

TECHNICAL SERVICES, Security Life Bldg. • Suite 1350 • 1616 Glenarm • Denver, Colorado 80202 • Phone. (303) 573-8027

Contractor <u>Rio Colorado</u>	Top Choke <u>1"</u>	Flow No. 1 <u>--</u> Min.
Rig No. <u>120</u>	Bottom Choke <u>1"</u>	Shut-in No. 1 <u>--</u> Min.
Spot <u>1985 FNL & 660 FWL</u>	Size Hole <u>7 7/8"</u>	Flow No. 2 <u>--</u> Min.
Sec. <u>2</u>	Size Rat Hole <u>--</u>	Shut-in No. 2 <u>--</u> Min.
Twp. <u>19S</u>	Size & Wt. D. P. <u>5" 19.5#</u>	Flow No. 3 <u>--</u> Min.
Rng. <u>30E</u>	Size Wt. Pipe <u>5" 32#</u>	Shut-in No. 3 <u>--</u> Min.
Field <u>Bone Springs</u>	I. D. of D. C. <u>2 1/2"</u>	Bottom Hole Temp. <u>116.8° F</u>
County <u>Eddy</u>	Length of D. C. <u>205.35 ft</u>	Mud Weight <u>9.8</u>
State <u>New Mexico</u>	Total Depth <u>9030 ft</u>	Gravity <u>--</u>
Elevation <u>3486.45 ft</u>	Interval Tested <u>6960-7020 ft</u>	Viscosity <u>34</u>
Formation <u>Upper Bone Springs</u>	Type of Test <u>Inflate</u>	Tool opened @ <u>--</u>
	<u>Straddle</u>	



Outside Recorder		
PRD Make <u>Kuster K-3</u>		
No <u>18079</u> Cap <u>4050</u> @ <u>6967'</u>		
Press	Corrected	
Initial Hydrostatic	A	--
Final Hydrostatic	K	--
Initial Flow	B	--
Final Initial Flow	C	--
Initial Shut-in	D	--
Second Initial Flow	E	--
Second Final Flow	F	--
Second Shut-in	G	--
Third Initial Flow	H	--
Third Final Flow	I	--
Third Shut-in	J	--
Lynes Dist. <u>Hobbs, NM</u>		
Our Tester <u>Charlie Freeburg</u>		
Witnessed By <u>Floyd Lowrey</u>		

Did Well Flow - Gas -- Oil -- Water --
 RECOVERY IN PIPE:

Misrun: Unable to obtain a packer seat.

Operator Arco Oil & Gas
 Address P.O. Box 1710
Hobbs, NM 88240
 Well Name and No. State 2 #1
 Ticket No. 02281
 Date 11-2-84
 DST No. 2
 No. Final Copies 9