



BENNETT-CATHEY WIRE LINE SERVICE

P. O. BOX 787
ARTESIA, NEW MEXICO 88210
Phone (505) 746-3281



BOTTOM HOLE PRESSURE SURVEY REPORT

OPERATOR SOUTHLAND ROYALTY
LEASE EAST MILLMAN 12 STATE COM.
WELL NO. 1
POOL FORMATION MORROW A
DATE 8-1-85 TIME 0919 HOURS
CO. MAN ED JACKSON
STATUS SHUT IN TEST DEPTH 10870'
TIME S.I. 1000 HRS LAST TEST DATE
7-31-85 BHP LAST TEST
TUB. PRES. 2753.2 BHP CHANGE
CAS. PRES. FLUID TOP
DATUM PLANE WATER TOP
DATUM PSIA 3765.2 RUN BY PETE HERNANDEZ
TEMP 198° CLOCK # 32160
PRESSURE RANGE 7100 #
ELEMENT NO. RPG3#46632

DEPTH	PSIA PRESSURE	LBS/100 FT GRADIENT
0	2753.2	
3000	3032.2	9.3
6000	3314.2	9.4
8000	3497.2	9.2
10720	3738.2	8.9
10870	3754.2	10.7
10964	3765.2	11.7

10964 FEET WAS EXTRAPOLATED

TIME B.H.P. MEASURED 0919 HOURS

LENGTH OF TIME WELL SHUT IN
23 HOURS 19 MINUTES

PERFORATIONS FROM 10958 TO 1097

2700 2800 2900 3000 3100 3200 3300 3400 3500 3600 3700 3800

