

RECEIVED BY

APR 21 1986

O. C. D.

ARTESIAN OFFICE

NM OIL CONS. COMMISSION

Drawer DD

UNITED STATES, NM 88210

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Form Approved.

Budget Bureau No. 42-R1424

NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☐

2. NAME OF OPERATOR

Robert N. Enfield

3. ADDRESS OF OPERATOR

P.O. Box 2431, Santa Fe, NM 87504-2431

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 660' FNL & 1980' FWL of Sec. 12

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐(other) SPUDDING & SURFACE CASING ☒

SUBSEQUENT REPORT OF:

☐☐☐☐☐☐☐☐5. LEASE
NM-14206

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
B & B Federal Comm.9. WELL NO.
110. FIELD OR WILDCAT NAME
Undesignated Penn11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 12, T19S, R26E12. COUNTY OR PARISH
Eddy13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3307.5 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 2:15 Pm 2/24/86. 17-1/2" hole was drilled to 328' K.B. 13-3/8" OD, 54.5#/ft., J-55, ST&C casing was run & cemented in place at 326.76' on 2/24/86.

Shoe & float collar were lock welded together.

Cemented w/300 sx Class "C" cement w/2% CACL2 (mixed 14.8#/gal., 1.32 cu. ft./sx yield).

Displaced plug w/44.3 barrels fresh water at 8 BPM, circulated 20 sx to pit. Bumped plug w/800 PSIG at 5:34 AM 2/25/86.

Waited 19-1/4 hrs., then began drilling out float equipment & cement.

Pressured up on casing for 3/4 hr. w/775-750 PSIG. Tested OK.

ACCEPTED FOR RECORD

Subsurface Safety Valve: Manu. and Type

APR 16 1986

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert N. Enfield

Operator

CARLSBAD, NEW MEXICO

DATE

4/10/86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

