

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ well ☐ other

2. NAME OF OPERATOR

Robert N. Enfield

3. ADDRESS OF OPERATOR

P.O. Box 2431, Santa Fe, NM 87501

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

1980' FNL & 990' FEL of Sec. 7

AT SURFACE

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) SURFACE CASING ☒

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM-29826

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Walters Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Undes McMillan U.Penn(Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T19S, R27E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3271' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well was spudded at 9:30 AM MDSL, 10/19/87. a 17-1/2" hole drilled to 320' KB where 13-3/8" casing was set & cemented as shown: All casing is 61.0#/ft., K-55 ST&C. Bottom to top: Texas pattern guide shoe (.80'), 1 jts. casing (46.73') 6 jts. casing (256.47'). Upon reaching set depth, hole circulated & fluids pumped as follows: 10 bbls fresh water, 350 sx Halliburton Premium Plus cement with 2% CaCl mixed 14.8#/gas, 1.32 cf/sx, 40.5 bbls fresh water. Plug bumped 5:00 Pm, 10/19/87; pressure released; float held. Full circulation observed throughout pumping operations. Approx. 25 sx cement circulated to pit. Cementing witnessed by Mr. Danny Cortez BLM. Casing pressure tested with 1000 PSIG; OK

SJS

* Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert N. Enfield

TITLE

DATE

Operator

11/16/87

Robert N. Enfield

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE