

BUREAU OF LAND MANAGEMENT

NM-67102

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different purpose. Use "APPLICATION FOR PERMIT" for such proposals.)

WELL ☒ GAS ☐ OTHER ☐

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

RECEIVED

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 37 below.)

1980' FNL & 1980' FWL, Unit Letter F

SEP 29 '88

O. C. D.
ARTESIA, OFFICE

1. IF APPLICABLE, ALLOTMENT OR LEASE NAME

2. UNIT ASSIGNMENT NAME

3. NAME ON LEASE NAME

Renegade Federal

4. WELL NO.

1

5. FENCE AND FENCE, OR WALKWAY

Parkway Delaware

6. SEC. T. R. M., OR R.M. AND QUAD OR AREA

Sec. 35: T19S, R29E

7. COUNTY OR PARISH

Eddy

8. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PILL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud & Surface Csg.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

37. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9/16/88 L&M Rig #1 spudded 17½" hole @ 4:15 PM & TD 358' @ 9:15 PM, (lost circulation @ 275', regained partial returns).

9/17/88 TOH w/drill string, ran 278' csg. & hit a bridge, TOH w/csg., TIH w/drill string ream hole to 358', RU & ran 8 jts. 13 3/8" 54.5# J-55 LS (364') set @ 357' KB, cemented w/215 sks 35/65 POZ, 6% D-20, 2% S-1, ¼# D-29, tailed in w/150 sks HEII, 2% S-1, ¼# D-29, plug down @ 11:30 AM, cement did not circ, ran 1" & cemented w/100 sks 6% D-20, 8% D-44, ¼# D-29, 200 sks Class C, 1% S-1, circ 10 sks to surface, finish 1" @ 5:45 PM, resume drlg.

RECEIVED

SEP 29 1988

38. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

V.P. Drilling & Production

DATE

9/20/88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 27 1988

*See Instructions on Reverse Side

SJS
CARLSBAD, NM 87501