

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-29228	
2. NAME OF OPERATOR Meridian Oil Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 21 Desta Dr., Midland, TX 79705		7. UNIT AGREEMENT NAME	
3a. AREA CODE & PHONE NO. 915/686-5600		8. FARM OR LEASE NAME Benson "3" Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SE/4 NE/4 Sec. 3, T19S, R30E		9. WELL NO. 2 & 3 Battery	
		10. FIELD AND POOL, OR WILDCAT Shugart (Y, SR, Q, G)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T19S, R30E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3440' GR.	12. COUNTY OR PARISH Eddy	13. STATE NM

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) **No Vent/Flare Extension**

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Authorization to vent/flare casinghead gas expires on 6/09/90. Authorization to vent/flare the casinghead gas for up to an additional 45 days or until on or about 7/24/90 is requested. The battery is located in the SE/4 NE/4 Sec. 3, T19S, R30E, Eddy County, NM. Meridian Oil Inc. has been informed by the gas gatherer that a line cannot be installed until "sometime in July". The gatherer is Phillips 66 Natural Gas Company. Phillips has indicated they will lay the line to their existing low-pressure system following the receipt of authorization to do so from the BLM. Current production from the battery is estimated to be 150 mcf casinghead gas.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert L. Bradshaw

TITLE

Sr. Staff Env./Reg. Spec.

DATE

04 June 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

***See Instructions on Reverse Side**