

c/ST

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
JUL 10 1991
O. C. D.
ARTESIA, OFFICE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address and Telephone No.
105 South 4th St., Artesia, NM 88210 (505) 748-1471

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FNL & 1980' FEL, Sec. 23-T20S-R24E, NMPM (Unit B)

5. Lease Designation and Serial No.
NM 045274

6. If Indian, Allottee or Tribe Name
N/A

7. If Unit or CA, Agreement Designation
N/A

8. Well Name and No.
Hill View AHE Fed. Com #6

9. API Well No.
30-015-26601

10. Field and Pool, or Exploratory Area
South Dagger Draw Upper Pen

11. County or Parish, State
Eddy, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other Spud, Set Surface Csg.
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded 20" hole 1:30 PM 5-24-91 with rathole. Set 40' of 20" conductor. Notified Duncan Whitlock, BLM, Carlsbad, NM, of spud. Resumed drilling 14-3/4" hole 7:45 PM 5-25-91. Notified BLM answering service, Carlsbad, NM. Lost circulation at 222'. Ran 28 joints 9-5/8" 36# J-55 casing set 1225'. Guide shoe set 1225', insert float set 1181'. Cemented w/200 sx Class "H" Gilsonite + 1/2#/sx Celloseal + 3% CaCl2 (yield 1.94, wt 12.4). Tailed in w/200 sx Class "C" with 2% CaCl2 (yield 1.32, wt 14.8). PD 8:45 PM 5-28-91. Bumped plug to 1100 psi, float held OK. Cement did not circulate. Cement top at 76'. Ready mix to surface. OK'ed by Don Early, BLM, Carlsbad, NM. WOC. Drilled out 3:00 PM 5-29-91. WOC 18 hrs and 15 minutes. Reduced hole to 8-3/4" and resumed drilling.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Production Supervisor Date 6-4-91

(This space for Federal or State office use)

Approved by _____ Title _____

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations in any matter within its jurisdiction.

*See Instruction on Reverse Side

ACCEPTED FOR RECORD

SSS

JUL 26 1991

CARLSBAD, NEW MEXICO