

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NUM.
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION		8. FARM OR LEASE NAME Hill View AHE Federal	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		9. WELL NO. 8	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 660' FEL, Sec. 14-20S-24E		10. FIELD AND POOL, OR WILDCAT South Dagger Draw Upper Penn	
14. PERMIT NO. 30-015-26602		11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA Unit P, Sec. 14-T20S-R24E	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3613' GR		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

RECEIVED

FEB - 4

O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded 26" hole 2:15 PM 1-6-91 with rathole. Set 40' of 20" conductor. Notified BLM, Carlsbad, NM, of spud. Resumed drilling 14-3/4" hole 8:00 AM 1-8-91. Notified Jim Amos, BLM, Carlsbad, NM. Ran 28 joints 9-5/8" 36# J-55 ST&C casing set 1206'. Guide shoe set 1206', insert float set 1164'. Cemented w/900 sx Lite, 10# Gilsonite, 1/2# Flocele + 3% CaCl2 (yield 1.9, wt 12.4). Tailed in w/200 sx "C" + 2% CaCl2 (yield 13.2, wt 14.8). PD 10:30 PM 1-10-91. Bumped plug to 400 psi, float held okay. Circulated 90 sacks cement. WOC. Drilled out 4:45 PM 1-11-91. WOC 18 hrs and 15 minutes. Reduced hole to 8-3/4" and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supervisor

DATE 1-30-91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE SJS

*See Instructions on Reverse Side