

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 660' FEL of Section 14-T20S-R24E (Unit P, SESE)

5. Lease Designation and Serial No.

NM-045274

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hill View AHE Fed #8

9. API Well No.

30-015-26602

10. Field and Pool, or Exploratory Area

Dagger Draw Upper Penn, So.

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Request Temporary Abandonment
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Yates Petroleum Corporation respectfully requests permission to Temporary Abandon this well for a period of one year in order to fully evaluate for workover and/or recompletion potential. Well will be temporary abandoned as follows:

1. TOOH with pumping equipment and tubing.
2. TIH with RBP and tubing. Set RBP at approximately 7540' (50' above Canyon perforations 7594-7752').
3. Load hole with packer fluid and conduct mechanical integrity test. Record on chart.

NOTIFY BLM-CARLSBAD (505-887-6544) AND OCD-ARTESIA (505-748-1283) IN SUFFICIENT TIME TO WITNESS MECHANICAL INTEGRITY TEST

14. I hereby certify that the foregoing is true and correct

Signed

Title Operations Technician

Date July 21, 1998

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

Approved by

Title PETROLEUM ENGINEER

Date JUL 29 1998

Conditions of approval, if any:

SEE ATTACHED FOR

CONDITIONS OF APPROVAL

Title 18 U.S.C. Section 101, makes it a crime for any person knowingly to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side