CISP

RECEIVED

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JAN 3 0 1992

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

O. C. D.

5. Lease Designation and Serial No. NM 043625

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE 1. Type of Well		7. If Unit or CA, Agreement Designation
Oil Gas Well Other		8. Well Name and No.
2. Name of Operator		Saguaro AGS Federal Com #10
YATES PETROLEUM CORPORATION (505) 748-1471		9. API Well No.
3. Address and Telephone No.		30-015-26852
105 South 4th St., Artesia, NM 88210		10. Field and Pool, or Exploratory Area South Dagger Draw U/Penn
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
Unit C, 660' FNL, 1980' FWL, Sec. 26-T20S-R24E		Eddy, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	☐ Plugging Back	Non-Routine Fracturing
—	Casing Repair	Water Shut-Off Conversion to Injection
Final Abandonment Notice	Altering Casing Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Spudded 26" hole 2:15 PM 12-16 ready-mix. Resumed drilling Ran 26 joints 9-5/8" 36# J-55 Cemented w/200 sx "H" w/12% Th 10#/sx Gilsonite, 1/2#/sx Cell + 2% CaCl2 (yield 1.33, wt 14. Cement did not circulate. WOC cement 227'. Spot 50 sx "C" + Pumped 230 sx "C" with 4% CaCl WOC 30 mins. Filled hole with	cal depths for all markers and zones pertinent to this work.)* -91. Set 40' of 20" conductor and center 14-3/4" hole 6:00 PM 12-17-91. casing set 1133'. Guide shoe set 1133 ickset + 2% CaC12 (yield 1.56, wt 14.50 oseal + 3% CaC12 (yield 1.94, wt 12.4) 8). PD 11:00 AM 12-19-91. Bumped plu 6 hrs. Ran Temp. survey and found TOC 4% CaC12. PD 6:00 PM 12-19-91. Ran 2. Circulated 5 sacks. Cement fell 3 100 sacks. Circulated 10 sacks (fill ut 9:00 aM 12-20-91. WOC 22 hours. If	3', insert float set 1099'. 5) and 700 sx Lite "C" + 1). Tailed in w/200 sx "C" 10g to 500 psi, held OK. 10g to 220'. Ran 1". Tagged 1". Tagged cement 162'. 1030'. PD 7:15 PM 12-19-91. 11 to surface at request of
14. I hereby certify that the foregoing is true and correct Signed (Antila) Wadlette	Title Production Supervisor	Date1-6-92
(This space for Federal or State office use)		
Approved by	Title	Date