

+ d5f
up

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87501

SEP 23 1992

O. C. D.

WELL API NO.
30-015-26921

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Dagger ZW

1. Type of Well:
OIL ☒ GAS ☐ OTHER ☐

8. Well No.
3

2. Name of Operator
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat
North Dagger Draw U/Penn

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter L : 1730 Feet From The South Line and 660 Feet From The West Line

Section 30 Township 19S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3568' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Spudded 10:00 AM 8-28-92. Set 40' of 20" conductor and cemented to surface. Notified NMOCD, Artesia, NM of spud. Resumed drilling 14-3/4" hole 4:15 PM 8-31-92. Lost circulation at 280'. Ran 25 joints 9-5/8" 36# J-55 casing set 1115'. Guide shoe set 1115', insert float set 1070'. Cemented w/200 sx "H" w/12% Thixad, 10#/sx Gilsonite, 1/2#/sx Celloseal + 1% CaCl2 (yield 1.62, wt 14.3). Tail in w/900 sx PSL "C" w/3% CaCl2 (yield 2.02, wt 14.8). PD 2:58 AM 9-2-92. Bumped plug to 800 psi, float held, Cement did not circulate. WOC 5 hrs. Ran Temperature Survey and found TOC 230'. Ran 5 stages of 1". Cemented w/250 sx Class "C" + 4% CaCl2. On stage 6, tagged cement 115'. Spotted 8-1/2 yds Readmix concrete down backside. Cement to surface. PD 2:55 PM 9-2-92. WOC. Drilled out 4:30 AM 9-3-92. WOC 25 hrs and 30 minutes.. Reduced hole to 8-3/4" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-22-92
TYPE OR PRINT NAME: Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II
APPROVED BY _____ TITLE _____ DATE SEP 28 1992
CONDITIONS OF APPROVAL, IF ANY: _____