

+ clsr  
DP

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26978
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <b>RECEIVED</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <b>O. C. D.</b> Thomas AJJ Com
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 5
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat North Dagger Draw U/Penn
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3553' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 3:34 PM 4-15-92. Set 40' of 20" conductor pipe. Notified Mike Stubblefield NMOCD, Artesia, NM of spud. Resumed drilling 14-3/4" hole 8:00 AM 4-18-92. Lost returns at 495'. At 1089' - no returns. TD 14-3/4" hole 4-19-92. Ran 25 joints 9-5/8" 36# J-55 ST&C casing set 1089'. Guide shoe set 1089'. Insert float set 1046'. Cmt'd w/200 sx "H" w/12% Calseal, 1/2#/sx Flocele, 10#/sx Gilsonite and 3% CaCl2 (yield 1.2, wt 14.4), plus 700 sx "C" w/1/2#/sx Flocele + 10#/sx Gilsonite + 3% CaCl2 (yield 1.84, wt 12.4). Tail in w/200 sx "C" + 2% CaCl2 (yield 1.32, wt 14.8). PD 9:15 PM 4-19-92. Bumped plug to 350 psi, held OK. Cement did not circulate. WOC 6 hrs. Ran Temperature Survey and found TOC 310'. Ran 6 stages of 1". Cemented w/400 sx Class "C" + 3% CaCl2. PD 12:00 PM 4-20-92. WOC 4 hrs. Circulated 20 sacks of cement on 6th stage. WOC. Drilled out 12:05 AM 4-24-92. WOC 26 hrs and 55 minutes. NU and tested to 1000 psi for 15 minutes. Reduced hole to 8-3/4". Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-24-92  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 8 1992

CONDITIONS OF APPROVAL, IF ANY: