

RECEIVED

FEB 15 1993

Form C-103
Revised 1-1-89+ dfr
upSubmit 3 Copies
to Appropriate
District OfficeState of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-27087	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	

7. Lease Name or Unit Agreement Name John "AGU"	
8. Well No. 7	
9. Pool name or Wildcat South Dagger Draw Upper Penn	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>14</u> Township <u>20S</u> Range <u>24E</u> NMPM <u>Eddy</u> County	

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3635' GR	
--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Set Production Casing, Perforate, Trt <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8075'. Reached TD 1:00 PM 2-2-93. Ran 197 joints of 7" 23# and 26# J-55 and N-80 casing set 8075'. Float shoe set 8075', float collar set 8035'. DV tool set 5604'. Cemented in two stages. Stage 1 - 600 sx PP "C" w/8#/sx Silicalite, .6% Halad 322, .3% salt and 5#/sx Gilsonite (yield 1.84, wt 13.6). PD 11:00 PM 2-3-93. Circulated 125 sacks. Circulated thru DV tool 3-3/4 hrs. Stage 2 - 875 sx PP "C" w/5#/sx Gilsonite, 1/4#/sx Flocele (yield 1.92, wt 12.5). Tailed in w/100 sx Class "C" Neat (yield 1.32, wt 14.8). PD 4:00 AM 2-4-93. Bumped plug to 1600 psi, float and casing held okay. Circulated 180 sacks. WOC 18 hours. Drilled out DV tool at 5604'. Perforated 7676-7756' w/38" - .50" holes as follows: 7676, 78, 82, 84, 86, 88, 89, 7708, 10, 16, 18, 20, 24, 26, 28, 51, 52, 54 and 7756' (perfs - 2 SPF). Acidized perfs 7676-7756' w/26500 gals 20% NEFE acid.

2-9-93. Turned well over to production to run pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 2-11-93

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE FEB 17 1993

CONDITIONS OF APPROVAL, IF ANY: