

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

NOV - 2 1992

O. C. D.  
APR 11 1993

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc. ✓

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980' FWL, SEC. 17, T-19S, R-25E, UNIT LTR 'C'

5. Lease Designation and Serial No.

NM 1372

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

COM # NMNM-85326

8. Well Name and No.

JENNY COM #2

9. API Well No.

30-015-27165

10. Field and Pool, or Exploratory Area

NORTH DAGGER DRAW PENN

11. County or Parish, State

EDDY CO. NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other SPUD SURFACE CSG

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

SPUD 10-25-92 AT 2 AM 13 1/2" HOLE.  
10-27-92 GIH W/ 29 JTS 9 5/8" 40# KD-95 BUTTRESS CSG SET AT 1071'.  
SHOE DEPTH @ 1050'. FIRST STAGE CMT. LEAD SLURRY 900 SX HALLIBURTON LITE W/  
3% CACL & 5# SX GILSONITE & 1/2# SX CELLO. TAIL SLURRY 200 SX CLASS C W/ 2% CACL.  
DISPLACED W/ 79.5 BBL FRESH WATER, CEMENT RETURNS OF 85 SX.  
CONTINUED DRILLING 8 3/4" HOLE.

14. I hereby certify that the foregoing is true and correct

Signed Paul T. Randolph

Title SR. REGULATORY SPEC

Date 10-29-92

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_