

YATES PETROLEUM CORPORATION
Hill View AHE Federal Com #17
Unit O, Section 23-T20S-R24E
Eddy County, New Mexico

DRILL STEM TEST

DST #1 5338-5420' (Bone Springs): TO 15"; SI 60"; TO 60"; SI 120"; TO 80".
Recovery: 282' of rathole mud and 2270' formation water. Sampler: Trace
of gas and 2600 cc water. Pressures: IHP 2560; IFP 166-425; ISIP 2384;
2nd FP 510-847; 2nd SIP 2384; FFP 878-1199; FHP 2560.