

C15F

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 710' FSL & 1980' FEL of Section 23-T20S-R24E (Unit 0, SWSE)	7. If Unit or CA, Agreement Designation
		8. Well Name and No. Hill View AHE Fed Com #17
		9. API Well No. 30-015-27214
		10. Field and Pool, or Exploratory Area Dagger Draw Upper Penn, So.
		11. County or Parish, State Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other <u>Change status from TA to Pressure Monitor Well</u>	<input type="checkbox"/> Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Yates Petroleum Corporation respectfully requests permission to change the status of this well from a Temporary Abandoned Well to Pressure Monitor Well.

3-4-98 - TOOH with rods and pump. TIH with packer and tubing. Set packer at 7530'. Loaded backside with packer fluid. Tested backside to 600 psi for 30 minutes, OK.  
PRESSURE MONITOR WELL - FINAL REPORT. NOTE: Notified OCD-Artesia and BLM-Carlsbad to witness Mechanical Integrity Test - did not witness.

Please see attached chart for Mechanical Integrity Test conducted on March 4, 1998.

APPROVED FOR 12 MONTH PERIOD  
ENDING 3/4/99

14. I hereby certify that the foregoing is true and correct		
Signed <u>Rusty Klein</u>	Title <u>Operations Technician</u>	Date <u>March 9, 1998</u>
(This space for Federal or State office use)		
Approved by <u>(ORIG. SGD.) ALEXIS C. SWOBODA</u>	Title <u>PETROLEUM ENGINEER</u>	Date <u>MAR 23 1998</u>
Conditions of approval, if any:		

