

YATES PETROLEUM CORPORATION  
Aparejo APA State Com #1  
Section 16-T19S-R25E  
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7762-7843' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120". RECOVERY: 911' of oil, 245' of rathole mud and 490' of water. SAMPLER: 2.71 cfg, 1300 cc water and 200 cc water. PRESSURES: IHP 3718; IFP 201-259; ISIP 2005; FFP 259-432; FSIP 2005; FHP 3718.

DST #2 7855-7884' (Canyon): Misrun - tool plugged.

DST #3 7855-7884' (Canyon): TIMES: TO 30"; SI 120"; TO 60"; SI 120". RECOVERY: 424' of mud cut formation water. SAMPLER: trace of gas and 2400 cc water. PRESSURES: IHP 3915; IFP 173-173; ISIP 2034; FFP 201-201; FSIP 1920; FHP 3915.