

YATES PETROLEUM CORPORATION  
Boyd X State Com #10  
Section 16-T19S-R25E  
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7676-7699' (Canyon Dolo): TIMES: TO 30"; SI 60"; TO 180"; SI 180".  
RECOVERY: 214' of oil and 3375' of mud and water. SAMPLER: 3.0 cfg, 150 cc of  
oil and 1750 cc water. PRESSURES: IHP 3802; IFP 403-721; ISIP 2120; 2nd FP  
750-1693; 2nd SIP 2120; FHP 3774

DST #2 7704-7755' (Canyon): TIMES: TO 30"; SI 60"; TO 180"; SI 180". RECOVERY:  
154' of oil and 176' of rathole mud and 1393' of water. SAMPLER: 3.7 cfg, 100  
cc oil and 900 cc water. PRESSURES: IHP 3802; IFP 201-403; ISIP 2120; 2nd FP  
259-837; 2nd SIP 2120; FHP 3774