

YATES PETROLEUM CORPORATION
Boyd BN #2
Section 15-T19S-R25E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7660-7730' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120". RECOVERY: 238' of rathole mud and 4075' of filtrate. SAMPLER: trace of gas and 2600 cc of water. PRESSURES: IHP 3535; IFP 401-1025; ISIP 2604; 2nd FP 1127-1873; 2nd SIP 2570; FHP 3535.

DST #2 7706-7800' (Canyon): TIMES: TO 30"; SI 60"; TO 330'; SI 60". RECOVERY: 715' of rathole mud and 391' of oil. SAMPLER: 2.9 cfg and 150 cc of oil. PRESSURES: IHP 3605; IFP 173-201; ISIP 2205; 2nd FP 173-375; 2nd SIP 2291; FHP 3605.

DST #3 7834-7894' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY: 176' of rathole mud and 3383' of formation water. SAMPLER: 0 cfg and 2600 cc water. PRESSURES: IHP 3662; IFP 144-605; ISIP 2575; 2nd FP 1156-1214; 2nd SIP 2575; 3rd FP 1214-1523; FHP 3662.