

YATES PETROLEUM CORPORATION
Polo AOP Federal Com #6
Section 10-T19S-R25E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7632-7684' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 210". RECOVERY: 60' of rathole mud, 822' of oil and 2487' of formation water. SAMPLER: 1.66 cfg, 1000 cc oil and 1100 cc water. PRESSURES: IHP 3813; IFP 619-822; ISIP 1652; 2nd FP 677-1568; 2nd SIP 1624; FHP 3813

DST #2 7692-7740' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY: 105' of rathole mud and 1353' of formation water. SAMPLER: .16 cfg and 2400 cc water. PRESSURES: IHP 3776; IFP 166-292; ISIP 1866; 2nd FP 224-583; 2nd SIP 1742; FHP 3776

DST #3 7746-7795' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY: 2011' of oil and 1624' of formation water. SAMPLER: 3.20 cfg, 900 cc oil and 700 cc water. PRESSURES: IHP 3859; IFP 375-548; ISIP 2120; 2nd FP 605-1354; 2nd SIP 2120