

YATES PETROLEUM CORPORATION
Boyd BN #5
Section 14-T19S-R25E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7660-7715' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 150' of gas cut mud. SAMPLER: .35 cfg and 600 cc mud. PRESSURES:
IHP 3664; IFP 212-145; ISIP 884; 2nd FP 145-145; 2nd SIP 1202; FFP 145-145;
FHP 3664

DST #2 7755-7813' (Canyon): TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY:
546' of oil and 490' of mud. SAMPLER: 1.04 cfg, 1150 cc oil and 350 cc water.
PRESSURES: IHP 3723; IFP 179-179; ISIP 2315; FFP 179-344; FSIP 2252; FHP 3723

DST #3 7816-7860' (Canyon): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 3702' of water. SAMPLER: 5500 cc water. PRESSURES: IHP 3811;
IFP 179-600; ISIP 2315; FFP 758-1234; FSIP 2315; FFP 1329-1649