

WELL TEST INTERPRETATION REPORT #:1078532		PAGE: 2,
CLIENT : OXY USA INC		13-NOV-97
REGION :CSD	SEQUENCE OF EVENTS	FIELD: BURTON FLATS
DISTRICT: HOBBS		ZONE :
BASE :MIDLAND		WELL : PEARL ST #1
ENGINEER: C. TAYLOR		LOCATION: S32T19SR29E

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
=====					
05-NOV	10:23	Gradient Stop 0 Ft.	-1280	423	
	10:48	Gradient Stop 2500 Ft.	-1255	686	
	11:07	Gradient Stop 5000 Ft.	-1236	769	
	11:21	Gradient Stop 7500 Ft.	-1222	886	
	11:36	Gradient Stop 10000 Ft.	-1207	1010	
	11:51	Gradient Stop 11175 Ft.	-1192	1079	
	15:18	START DATA ACQUISITION	-985	1071	
06-NOV	07:43	END FLOW & START SHUT-IN	0	1051	
11-NOV	13:10	END SHUT-IN	7527	4192	
	13:13	Gradient Stop 11175 Ft.	7530	4192	
	14:11	Gradient Stop 10000 Ft.	7588	4079	
	14:20	Gradient Stop 7500 Ft.	7597	3870	
	14:30	Gradient Stop 5000 Ft.	7607	3651	
	14:38	Gradient Stop 2500 Ft.	7615	3425	
	14:51	Gradient Stop 0 Ft.	7628	3199	
	08:06	START FLOW	7223	4207	
	11:02	CHANGED CHOKE	7399		
	11:58	CHANGED CHOKE	7455		
	12:59	CHANGED CHOKE	7516		
	13:51	END FLOW	7568	2787	