

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

11 S
Artesia, NM

vision

34

FORM APPROVED
OMB No. 1004-0134
Expires July 31, 1994

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **657**
NM 042857

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
OXY USA INC.

16696

3a. Address **P.O. BOX 50250**
MIDLAND, TX 79710-0250

3b. Phone No. (include area code)

915-685-5717

8. Well Name and No.
OXY Ribeye Federal #1

9. API Well No.
30-015-30173

10. Field and Pool, or Exploratory Area
Winchester Morrow

11. County or Parish, State

EDDY NM

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650 FNL 1980 FNL SENW (F) Sec 34 T19S R28E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other **Spud, Set**

Csg & Cmt.

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Other Side

ACCEPTED FOR RECORD

JUL 01 1998

BLM

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

DAVID STEWART

Title

REGULATORY ANALYST

Signature

David Stewart

Date

6/25/98

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Office certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ATTACHMENT 3160-5
OXY USA INC.
OXY RIBEYE FEDERAL #1
SEC 34 T19S R28E
EDDY COUNTY, NM

NOTIFIED BLM 5/29/98 OF SPUD. MIRU MCVAY #10, SPUD WELL @ 1130hrs MDT 5/31/98. DRILL 17-1/2" HOLE TO 180', LOST ALL RETURNS. M&P LCM SWEEP WITH NO SUCCESS, DRY DRILL TO TD @ 423', 5/31/98, M&P LCM PIL. RIH W/ 13-3/8" 48# H40 CSG & SET @ 423'. M&P 200sx CL H W/ 9% A-10B + 10#/sx GILSONITE + .25#/sx CELLOFLAKE + 1% CaCl_2 , FOLLOWED BY 220sx 65/35-C/POZ W/ 5#/sx GILSONITE + 2% CaCl_2 + .25#/sx CELLOFLAKE FOLLOWED BY 200sx CL C W/ 2% CaCl_2 , DISP W/ FW, PLUG DOWN @ 0330hrs MDT 6/1/98, CEMENT DID NOT CIRCULATE, WOC 4hrs. NOTIFIED BLM, DON EARLY WITNESSED PART OF CEMENT JOB. RIH W/ 1" & TAG CMT @ 90', M&P 50sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 90', M&P 30sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 77', M&P 30sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 77', M&P 30sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 72', M&P 30sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 70', M&P 80sx CL C W/ 4% CaCl_2 , WOC. RIH & TAG CMT @ 70', M&P 50sx CL C W/ 4% CaCl_2 , WOC. CIRC 12sx CMT TO PIT. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 900#, OK. NU BOP & TEST TO 1500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD.

DRILL 11" HOLE TO TD @ 3000', 6/5/98, PUMP SWEEP, RIH W/ FCL. RIH W/ 8-5/8" 24-32# CSG & SET @ 3000'. M&P 900sx 65/35/6-C/POZ/GEL + 5#/sx SALT + 5#/sx GILSONITE + .25#/sx CELLOFLAKE FOLLOWED BY 200sx CL C W/ 2% CaCl_2 , DISP W/ FW, PLUG DOWN @ 2310hrs MST 6/5/98, CIRCULATE 231sx CMT TO PIT, WOC 8hrs. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS & CUT CSG. NU BOP & TEST TO 5000#, OK. RIH & TAG, DO CMT, TEST TOO 500#, OK, DRILL AHEAD.

REC'D
JUN 26 1998
EDDY COUNTY, NM

JUN 26 1998

REC'D