

YATES PETROLEUM CORPORATION
Triangle Ranch ASW State Com #1
Section 13-T19S--R23E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 8305-8389' (Lower Morrow): TIMES: TO 15"; SI 90"; TO 60"; SI 300".

RECOVERY: 114' of slightly gas cut mud. SAMPLER: 1.62 cfg & 25 cc mud.

PRESSURES: IHP 4222; IFP 98-115; ISIP 3042; FFP 177-199; FSIP 3195; FHP 4227