


**BOP DIAGRAM**

**3000# WORKING PRESSURE
RAMS OPERATED DAILY**

**EAST MILLMAN POOL UNIT NO. 4-12
EDDY COUNTY, NEW MEXICO**

EXHIBIT NO. 1