

WELL TEST INTERPRETATION REPORT #:6185247		PAGE: 3,
CLIENT : TORCH OPERATING COMPANY		22-MAY-***
REGION : CSD	SEQUENCE OF EVENTS Continued	FIELD: TURKEY TRACK
DISTRICT: HOBBS.		ZONE : ATOKA
BASE : MIDLAND		WELL : SPUR 11 ST-1
ENGINEER: J. DAUGHERTY		LOCATION: S11T19SA29E

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
	01:16	175.25 "	228		115.0
	01:21	175.25 MCFD	233		115.0
	01:21	END FLOW & START SHUT-IN	233	271	
	09:09	END SHUT-IN	701	1004	
	09:15	HYDROSTATIC MUD	707	5306	