

WELL TEST INTERPRETATION REPORT #: 6185247		PAGE: 2,
CLIENT : TORCH OPERATING COMPANY		22-MAY-88
REGION : CSD	SEQUENCE OF EVENTS	FIELD: TURKEY TRACK
DISTRICT: HOBBS		ZONE : ATOKA
BASE : MIDLAND		WELL : SPUR 11 ST-1
ENGINEER: J. DAUGHERTY		LOCATION: S11T19SA2SE

DATE	TIME	DESCRIPTION	ET	BHP	WHP
	(HR:MIN)		(MINS)	(PSIA)	(PSIG)
=====					
21-MAY	21:20	HYDROSTATIC MUD	-8	5299	
	21:28	START FLOW ON 1/8" HOSE	0	108	
	21:29	BOTTOM OF BUCKET	1		
	21:30	13.0 oz	2		
	21:31	18.5 oz	3		
	21:32	SURFACE READINGS TO PSI	4		1.4
	21:33		5		2.2
	21:38		10		4.2
	21:43		15		9.4
	21:44	END FLOW & START SHUT-IN	16	130	
	22:30	GAS TO SURFACE	32		
	22:44	END SHUT-IN	76	1003	
	22:46	START FLOW ON 1/4" TO PIT	78	85	
	22:47	28.23 MCFO	79		6.4
	22:48	30.11 "	80		7.8
	22:49	32.26 "	81		9.4
	22:50	33.60 "	82		10.4
	22:51	35.48 "	83		11.8
	22:56	42.46 "	88		17.0
	23:01	49.18 "	93		22.0
	23:06	55.90 "	98		27.0
	23:11	63.98 "	103		33.0
	23:16	69.37 "	108		37.0
	23:26	82.86 "	118		47.0
	23:36	95.03 "	128		56.0
	23:46	107.21 "	138		65.0
	23:56	119.41 "	148		74.0
22-MAY	00:06	130.27 "	158		82.0
	00:16	139.79 "	168		89.0
	00:26	147.96 "	178		95.0
	00:36	154.77 "	188		100.0
	00:46	161.59 "	198		105.0
	00:56	168.42 "	208		110.0
	01:06	175.25 "	218		115.0

Continued next page