

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 066133

Unit Texas Hill

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

H. W. Ross Co.

Hobbs, New Mexico

July 25, 1951

Well No. 1 is located 400 ft. from N line and 850 ft. from E line of sec. 5.

SE/4 Sec. 5
(1/4 Sec. and Sec. No.)

22-S
(Twp.)

21-W
(Range)

N. 10. 10. 10.
(Meridian)

131dca
(Field)

Body
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 16" casing at 45' with 175 sacks cement, cement circulated to surface.
Job complete at 3:00 A.M. 7-12-51.

On 7-12-51, after 24 hrs. rest, drilled out cement to total depth and bailed hole dry. Waited 1 hour before drilling resumed, test satisfactory.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 66

Hobbs, New Mexico

By _____

Title District Superintendent