

Form 5-341
(May 1964)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Only in triplicate on 11
vertical)

SLUP

Copy to SF

Form approved
Budget Bureau No. 42-1-11
5. FIELD IDENTIFICATION AND LOCATION NO.
NM 11382
6. IF 15043, ALLOCATION OF THE 7.00

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Salt Water Disposal well</u>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Continental Oil Company</u>	8. FARM OR LEASE NAME <u>Spring (SWD)</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, New Mexico 88240</u>	9. WELL NO. <u>1 (SWD)</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 15 below.) At surface <u>660' FNL and 830' FEL of Section 4, T-21S, R-25E</u>	10. FIELD AND TOWN OR VILLAGE <u>Upper Pecos</u>
14. PERMIT NO.	11. SEC. T., R., S., OF BLM AND SURVEY OR AREA <u>Sec. 4, T-21S, R-25E</u>
15. ELEVATIONS (Show whether at, by, or, etc.) <u>3304 DF</u>	12. COUNTY OR PARISH <u>Eddy</u>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	13. STATE <u>N. Mex.</u>

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
 FRACTURE TREATMENT ☐
 SHOOT OR ACIDIZE ☐
 REPAIR WELL ☐
 (Other) ☐

PULL OR ALTER CASING ☐
 MULTIPLE COMPLETION ☐
 ABANDON* ☐
 CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
 FRACTURE TREATMENT ☐
 SHOOTING OR ACIDIZING ☐
 (Other) Connect to SWDW

REPAIRING WELL ☐
 ALTERING CASING ☐
 ABANDONMENT* ☒

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per-
tinent to this work.)

Connected Springs no. 1 to SWDW. Spotted 45' at 10, 130'. Perf. 5 1/2" Csg @ 8316, 21, 33, 36, 40, 46, 52, 59, 65, 73, 77, 81, 86, 97, + 8400' w/ 5.5" F. Spotted 15' LSTNE over Perf. 8316-8400', Displaced hole w/ TATD WTR. Ran 2" Plastic lined tubing, set at 8252'. Injected 527 bbls, Wtr. in 24 hrs. Pump Pressure 95 PSI.

RECEIVED

JUN 12 1970

O. C. C.
ARTESIA, OFFICE

RECEIVED

JUN 11 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Adm. Section ChiefDATE 6-10-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

ART USGS-5 FILE
Woods R. Co.

R. L. BECKMAN *See Instructions on Reverse Side