



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. _____

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1-Reader 920 2310 1919

Sec 19 NE 1/4 20 South, 26 East N. W. P. [H] ft. from [W] line of sec.

Well No. is located [S] line and

wild-cat Eddy New Mexico

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

3267

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

DETAILS OF WORK
We ran heavy mud from 827' total depth to 925'; cement plug to 550'; heavy mud to 10' below cement plug; set a 10" casing at 316'; ran heavy mud to 200'; cement plug to 165'; heavy mud to within 6' of surface where we set a 4" steel marker, 6' in cement and 6' above ground.

RECEIVED
C. J. H. SURVEY
ARTESIAN WATER DIVISION

Robt. W. Allen

I understand that this work must receive approval in writing by the Geological Survey before operations may be commenced.

Company

Address

By

Title