

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

Company Everett D. Burgett 102 S. Canal, Carlsbad, N. Mex.
(Address)
Lease E-2597 Pure State Well No. 8 Unit J S 15 T 21 E R 27 S.
Date work performed 8/20/55 POOL Magruder-Yat

This is a Report of (Check appropriate block) ☐ Result of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other casing well

Detailed account of work done, nature and quantity of materials used and results obtained. Pure No. 8 cased in between 75' and 125' the well was drilled out and 210' of 8 1/2" pipe, 142 lb wt. was run, and cemented with 20 skgs of cement by Denton Cementing Co. Put back on pump 8/20/55

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____
Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____
Perf. Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

Oil Conservation Commission

Name L. A. Hanson

Title _____

Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Everett D. Burgett

Position operator

Company Lann