

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Everett D. Burgett
(Address)

LEASE Pure State WELL NO. 72 UNIT 0 S 15 T 21 R 27

DATE WORK PERFORMED Completed 12/2/57 POOL Magruder Yates
11/30/57

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☒ Remedial Work
☐ Plugging ☒ Other repairing casing

Detailed account of work done, nature and quantity of materials used and results obtained.

Pump was being pulled and was hung on the top two joints of casing which came unscrewed when these were pulled the surface sand and red bed fell in. The well was then cleaned out the pipe rerun and 10 sacks of cement was pored in on the out side of the pipe this filled up to within 15 ft. of the surface there was no cement that ever came into the well the bottom of the pipe set in mud when the well was completed still had a good shut off the pipe is well tied in so that this will not happen again. The pump was again run and turned into the tank on 12/2/57

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____

Witnessed by _____ (Company)

OIL CONSERVATION COMMISSION

Name M. L. Armstrong
Title OIL AND GAS INSPECTOR
Date DEC 11 1957

I hereby certify that the information given above is true and complete to the best of my knowledge

Name Everett D. Burgett
Position operator
Company same