


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 1 is located 600 ft. from S line and 1900 ft. from W line of sec. 11
1/4 Sec. 11 (1/4 Sec. and Sec. No.)
200 (Twp.) 25 (Range) 100M (Meridian)
McNeill pool (Art) (Field) Indy (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to T.D. 910'. Stopped hole to base of Salt at 550'. Set 50' cement plug. Stopped hole to 450'. Set 50' cement plug. Cut 5 5/8" casing off at 103' from surface - raised hole to surface and set marker in cement.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kersey & Donohue

Address Box 305
Artesia, New Mexico

By Harold Kersey
Title Partner