

# VISION ENERGY, INC.

P.O. BOX 2459 • CARLSBAD, NM 88221-2459 • (505) 236-6041

New Mexico Oil Conversation  
District II Office  
811 S First Street  
P.O. Drawer DD  
Artesia, New Mexico 88220

RECEIVED

APR 29 1992

O. C. D.  
DISTRICT OFFICE

Attn. Mike Williams

Date: April 28, 1992

Re: Vision Energy, Inc.  
State #1  
Unit M Sec. 21, T-20S, R-28E  
Eddy County, NM  
Wildcat Yates Formation

Mr. Williams

Vision Energy, Inc. attempted to test the seven inch production casing in the State #1 on April 27, 1992. The test was conducted as follows.

1. Shut in tubing pressure 280 PSI
2. Shut in casing pressure 0 PSI
3. Installed pressure recorder on casing
4. Loaded Csg (Via contract hot oil truck) with Approximately 1.5 Bbls fresh water. Casing capacity above AD packer 16.5 Bbls.
5. Pressured to 200 PSI pressure leaked off to 100 psi in approximately one minute.
6. Pressured to 300 PSI pressure leaked off to 100 psi in approximately one and a half minutes.
7. Pressured to 400 PSI pressure leaked off to 100 psi in approximately two minutes.
  - A. Each time we repressured it only took a few pump strokes to pressure and we were unable to establish a rate.
  - B. Valves were checked for leak back, and none was found.
  - C. Test was aborted and it was determined that there was a csg leak, with no communication below the packer or to the surface.