



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office **Las Cruces**
Lease No. **LC 065028**
Unit **RECEIVED**

DEC 21 1959

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Plugging X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 28, 1959

Vickers
Well No. **2** is located **330** ft. from **N** line and **1650** ft. from **E** line of sec. **23**
NW/4 NE/4 Sec. 23 **208** **28E** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Russell **Eddy** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 10 sack cement plug was placed in the bottom of hole at 900'.
A 10 sack cement plug was placed in bottom of pipe at 650'. Cut
and pulled casing - 10 sack cement plug in stub of pipe at 230' with mud
between plugs. Cemented marker and sign.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Mr. H. G. Wells**
Address **3001 Aurora St.**
El Paso, Texas

By **[Signature]**
Title **Clerk**