



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office NEW MEXICO

Lease No. LC 062254-A

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... November 15,, 1957.

1-Mayfield "X"

Well No. is located 1076 ft. from [N] line and 2286 ft. from [E] line of sec. 33

SW/4SE/4 33 20 S 28 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well was drilled to depth of 700'. 700' of 4" casing was set through 100' of 7" surface casing 30 sacks circulated to set casing. Bottom 40' of casing was perforated before setting. Well recovered 100' of fluid on 24 hour shut down, of which 75' was connate sulphur water and 25' oil (Approx. 1/2 bbl.) It is planned to fill hole with mud and set surface plug.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George E. Conley, et al.

Address Post Office Box 611
Sanl'a Fe, New Mexico

By _____

Title Operator