


(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. LC 062254(A)

Unit None



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 4, 1958.

Well No. 1 <sup>WXM</sup>Mayfield's located 1076 ft. from S line and 226 ft. from E line of sec. 33

SW 1/4 Sec. 4 33 20 S. - 20 E. N. M. P. M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Salado-yote Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

AMENDED REPORT

Total depth of hole 716'. 100' 7" surface casing and 580' 4" 9.5 lb. casing left in hole. 10 sacks plug at 600' - 680'; 5 sacks 300' - 345'. 3 sacks surface and 4' of 4" mother pipe set. Mud used between plugs.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George E. Conley, et al.

Address Post Office Box 247

Ontario, California

By Conley

Title Operator