

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land entry: LOS CRUCES  
Lands No. 997099  
Date 1948

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERNATE CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 3, 1948

Well No. 1 is located 1652 ft. from S line and 2326 ft. from E line of sec. 1

Sect. 1 T. 20 S. R. 29 E. N. M. P. M.  
(M. Sec. and Sec. No.) (Twp.) (Range) (Mention)

Wildcat Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show plans, weights, and lengths of proposed casings; indicate casing jobs, cementing points, and all other important proposed work)

At a total depth of 352', 8-5/8" used 28# lapweld casing was cemented by Halliburton with 50 sacks of cement. Cement set until 8-2-48, (72 hours) when plug was drilled and drilling resumed. Cement job was successful.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Neil H. Wills et al

Address Box 529

Carlsbad, New Mexico

By \_\_\_\_\_

Title \_\_\_\_\_