



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office _____
Lease No. 8-32666
Unit W.B. Healey

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 26, 1957

Well No. 1-A is located 335 ft. from [N] line and 1650 ft. from [E] line of sec. 5
20 South, 25 East S. 4. E.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox ddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3322 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was plugged as follows:

10 sec cement, plug was set on bottom -1315'.

10 sec cement, plug set at bottom 7-inch csg. -975'.

hole was filled with mud to surface, cap set, marker in place, location was cleaned and pits were filled. Location is now ready for inspection.

RECEIVED
NOV 26 1957

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Rebel Oil CompanyAddress Box 433,Artesia, New Mexico

By

Title

