

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa FeLease No. NW 01165

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
	<u>Flagging</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Yates
Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 8
SW/4 SW/4 Section 8 20S 29E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dartan (Ext) Lady New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

50' cement plug at bottom of hole at 1208. Mudded up to 840' and put 50' cement plug. Mudded back to 460' and placed 50' cement plug partly out of casing and in casing. Mudded hole back to surface and set marker in cement. Did not pull any of the 440' of 8 5/8" casing that was run in hole. Work discussed with supervisor prior to doing job.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Hersey & Company
Box 305
Address Artesia, New MexicoBy Harold Hersey
Title Partner