



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. UN 059162Unit K

RECEIVED

OCT 15 1962

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Final Report on Plugged Well <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 8, 1962

McKee
Well No. 1 is located 2310 ft. from N line and 2310 ft. from E line of sec. 11
NE 1/4 Sec. 11 20-S 29-E N.R.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Gatty Pool (Ext.) Sdday New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3303 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PLUGGING INFORMATION

Used pump truck and spotted cement plugs as follows. Space between plugs was filled with Gel Mud.

25 sack plug 1440-1515 (Gel Mud 1515-1540)

30 sack plug 1310-1400

35 sack plug 325-430

15 sack plug 100-130

10 sack plug at surface

Used collar buster and pulled 120' of 8 5/8" surface casing.
Regulation marker has been set and location cleaned up.

LOCATION IS READY FOR FINAL INSPECTION

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company James L. Lamb, Jr.Address Box 5305Midland, TexasBy James L. Lamb Jr.Title Owner