

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**  
Lease No. **029012**  
Unit **Fred I. Stebbins**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Artesia, New Mexico,**  
**July 31,**

19 **44**

Well No. **1** is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **29**  
**S. 29 S. 29 Sec. 29** **29 S.,** **29 E. N.W.P.M.**  
(14 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Wildcat** **Elly** **New Mexico.**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Cemented 620 feet of 8" casing with 50 sacks of cement, on July 13, 1944, with cementing done by Halliburton Oilwell Cementing Company. After standing 72 hours for cement to set, test by bailing showed complete water shut-off.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **MARTIN YATES, III, et al.**  
Address **Box 162,**  
**Artesia, New Mexico.**  
By **Martin Yates III**  
Title **partner.**