

(SUBMIT IN TRIPLICATE)

Land Office New Mexico

UNITED STATES

Lease No. 02508

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Unit Lot 11

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal Harris

May 16th

1957

Well No. 1 is located 2324.6 ft. from N line and 2310 ft. from W line of sec. 5

Lot 11 Sec 5 21S 20E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wilcox Wilcox New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3400 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We filled the hole with gel from 1908 back to 710 feet, set a bridge plug at 710 feet and cemented with 20 sacks cement. We then filled the hole with gel to the top, pulled the 10 3/4" casing and the 13 3/8" casing. We set a cement plug 10 feet below the surface, and cemented a 4 inch pipe in top of the hole for a marker. We then cleaned the location and left the ground in its original condition.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WILLIAM A. & EDWARD R. HUDSON

Address 1310 ELECTRIC BUILDING

PORT WORTH, TEXAS

By

Title

Partner