



GEOLOGICAL SURVEY  
DEPARTMENT OF THE INTERIOR  
UNITED STATES

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease No.

06297

Unit

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal # Lease

Well No. 3-28 is located 330 ft. from N line and 1900 ft. from E line of sec. 28

Sec. 28  
(Sec. and Sec. No.)

20-6  
(Twp.)

30-E  
(Range)

N.H.P.M.  
(Meridian)

New Mexico  
(Field)

Eliz  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3952 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This test was spudded 12-13-56, drilled to a depth of 385', and plugged and abandoned there, due to an excessively crooked hole.

Plugging was done 12-14-56, by pumping a 15 sack plug 385' to 355'. The hole was then bridged at 25' and a 10 sack plug was pumped in, bringing the cement up into the cellar.

The rig was then skidded 30' due west.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John R. Tripp Company

Address P. O. Box 5629

Lawell, New Mexico

By

Title

Geologist

ILLECIBLE